

SPRAY PAINT G7000

DESCRIPTION

G7000 is a cost effective, general purpose, fast drying, excellent weather/water resistance, good leveling, strong covering power spray paint. It can be used in a variety range of metal, surface treatment of wood, glass, ABS plastic and other substrate coating.

FEATURES

Environmental, non-toxic, odorless after dry, spray rate can reach to 99.9%, excellent weather resistance, excellent light and excellent color performance, good resistance to chemical and water resistance, good adhesion with proper primer, good leveling, strong covering power, good polishing, colorful, color is positive and fast drying.

APPLICATION

It can be used in a variety range of metal, surface treatment of wood, glass, ABS plastic and other substrate coating.

TECHNICAL DATA

Standard:	BB/T 0047-2007
Materials:	Acrylic Resins, Additive, Solvent, Pigment, and DEM/LPG Propellant.
Color:	Normal spray paint/fluorescence automatic spray/metal spray paint/plating color automatic spray paint
State:	liquid
Tack free time:	8-15 minutes
Hard-dry time:	30-60 minutes
Spray rate:	>99%
Spray speed:	>1.5g/s
Coverage:	about 2-2.5 square meters
Temperature resistance°C:	-30~+70
Application temperature°C:	-15~+45

PACKAGING

- **Package:**
- 12 pieces/carton
- Tin Dimension: 6.5*6.5*20cm

- Carton Dimension: 27*21*21cm
- 2650 cartons in 1*20ft container
- 6500 cartons in 1*40ft container

WEIGHT

- 240g /piece gross weight
- Net weight/carton: 2.88 KGS
- Gross weight/carton: 3.08 KGS

TRANSPORT AND STORAGE

- Transported as hazardous products.
- Store in room temperature (<40°C) and a well-ventilated place, away from heat, open flames or other sources of ignition.
- Shelf life: 36 months

OPERATION NOTICE

- 1.The material surface has to be free of any dirt, grease, rust etc.
- 2.Mask off adjacent panels to prevent over spray.
- 3.Shake can vigorously for about 30 seconds.
- 4.Hold the can 20cm from the surface to be sprayed. Press the nozzle and spray using a uniform hand motion.
- 5.Several thin coats applied at an intermitten 3 minutes are better than one heavy coat.
- 6.After use, clean the valve by turning the can upside down and pressing the nozzles for about 3 seconds to prevent clogging.
- 7.Before disposing finished cans, turn the aerosol can upside down and firmly press the nozzle until remaining paint is emptied. If necessary, pull out the nozzle to clear.
- 8.For best results, do not apply during rainy days of humid environment (RH≥80%). Test on a small area before actual application.

CAUTION

- 1.Store in room temperature(<40°C) and a well-ventilated place, away from heat, open flames or other sources of ignition.
- 2.Avoid spraying into eyes or swallow.
- 3.Do not incinerate or puncture aerosol cans.
- 4.Keep out of reach of children